

CQSDI 2000



NASA Failure Detection and Prevention Program: Risk Identification and Management Tools -

Risk Balancing Profiles (RBP)
Defect Detection and Prevention (DDP)

Timothy W. Larson
Jet Propulsion Laboratory
California Institute of Technology
(818) 354-0100
timothy.larson@jpl.nasa.gov

March 7, 2000



FDP Program




- Failure Detection and Prevention Program (FDPP) new program begun in FY99, funded by NASA Office of Safety and Mission Assurance (Code Q)
- Jointly performed between JPL, GRC, GSFC
- Goal is to develop tools that will aid in the identification and management of technical risk
- Developing three primary tools/products:
 - Risk Balancing Profiles
 - Defect Detection and Prevention (DDP) Tool
 - Assurance Effectiveness Guidebook
 - These tools will be combined into one tool by Sept. 2000



The Challenge





• The Challenge

With limited resources, how is a balanced risk management approach selected to control the residual risk to mission success caused by the presence of known potential failure modes?


• The Approach

Develop tools which address residual risk as a function of various risk control options. Options exist at the planned activity level and in the degree to which potential failure modes are addressed



FDPP and the Project Life Cycle







Risk Balancing Profiles




- A tool that aids in the development of assurance program plans
- Provides a mechanism for identifying technical performance risk associated with program content
- Aids in identifying mitigation possibilities corresponding to residual risk
- Assists assurance program planning by:
 - enabling the identification of specific risk areas correlated to the chosen program content
 - identifying areas to be discussed with subject experts to further refine program
 - resulting in rationale for chosen program content and accepted risk
 - providing a tool to balance risk and resources rationally



RBP - The Problem:





Selected program is based on balance of available resources and acceptable risk, influenced by mission requirements and characteristics



Contact Information



- For information regarding the FDP Program or the RBP Tool:
 - Mr. Timothy Larson
 - (818) 354-0100
 - timothy.larson@jpl.nasa.gov